

AGENDA ITEM 6: New Matters – Appendix C

Reference	Location	Description	Actions
180918/01	Parking on Bridge Road	A local resident from St Andrews Road is very concerned at the level of parking by business staff and customers on Bridge Road. On any given day, there are 12-15 vehicles parked on and around St Andrews road at Garrison Lane end. They are parked right up to the corner, on the pavements at the corner, on the corners of Princes Road and using spaces outside of houses. This is causing considerable danger to vehicles pulling into St Andrews road and any vehicle pulling out of Princes Rd onto St Andrews. There is ample parking for staff and customers at Bridge Road.	
Update		Update PG 13/9: If this is an issue of inappropriate parking then it will be a police matter. TRO's could be looked at if appropriate. PG will look today and report back.	
180918/02	Access to the Prom between Cobbold's Point and Bath Hill	A member of the public has asked if it is possible to have the areas where the promenade has been lowered for wheelchair access to be made more visible so drivers will not park there. This is specifically about the area between the sea front end of Maybush Lane and Bath Hill.	
Update		Update PG 13/9: PG will look at today and report back.	
180918/03	Poor surface from No 49 to 97 eastbound (opposite Colneis Junior School)	Numerous potholes over this extent of road have been patched in recent years, leaving a very undulating and crazed surface, in particular around the pedestrian and other crossing points to the school.	
Update		Update PG 13/9: PG will look at today	

AGENDA ITEM 6: New Matters – Appendix C

180918/04	Garrison Lane (Langer Road to High Road West)	Garrison Lane (Langer Road to High Road West) not swept after surface dressing work which has proved a hazard to elderly pedestrians, mobility scooter and rollator users .	
Update		Update PG 13/9: If the work was done this year then the contractor can be asked to come out to sweep. However, SCNorse should be sweeping that road.	
180918/05	Grange Rd (odd numbered side between 115 & 129 Vicarage Rd to Mill Lane)	Pavements require attention	
Update		PG will investigate	
180918/06	Hamilton Road	Reinstatement of pavement regarding tree knocked down by First Bus near 116-120 in April 2017	
Update		PG will investigate, and would like confirmation that it was First Bus.	
180918/07	Candlet Road	The kerbside overgrowth needs cutting back between the Docks Spur roundabout and the Gulpher Road overbridge.	
Update		Update PG 13/9: PG will look at today	